5

ABSTRACT OF THE DISCLOSURE

A surface of a commutator 5 is rubbed by a shakedown brush 21 other than ordinary brushes 11 to produce a carbon coat, whereby a shakedown process can be reduced or abolished.